

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	002	012	0000000538	0031.2500	Circuit Protection	FUP	
				0031.2510			
				0031.2520			

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

The inscription at the socket of the fuseholder changes. The voltage rating acc. to UL/CSA is new 600V.

3 Detailed description of change

The inscription changes as follows.

Old inscription	New inscription
	

4 Reason of change

The fuseholder FUP has a voltage rating acc. to UL 4248-1 / CSA C22.2 no 4248.1 of 600V (AC/DC). This rating is corrected on the inscription of the socket. Because of this, the layout of the inscription changes.

5 Release date

The change will be rolled-out starting in August 2015, depending on the stock.

6 Impact of change and recommended action

Form: Yes (inscription only)
Fit: No
Function: No
Production Site: No
Product Label: No

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet	FUP	Web Link FUP

FUP					0118.2214	
creation date	created by	release date	released by	notification no.	revision	page
2014-05-23	dislercy	2014-09-01	dislercy	26340	-	1 of 1