

International Rectifier

101 North Sepulveda Boulevard, El Segundo, California, 90245, USA Telephone: +1 310 726 8000 www.irf.com

Process Change Notification

Date: Monday, July 20, 2015

PCR Reference: 611

PCN Reference: 611-PCN90-Public

To Our Value Customer:

As always we appreciate your use of International Rectifier semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our change plans to enhance capacity, quality and reliability. This notice is to inform you of the following changes.

We would like to express our sincere appreciation for your cooperation regarding the following changes, and IR will work closely with you to support your requirements during this transition.

Type of Change Notification:

Alternate site for the assembly and test

Description of Change:

QFN-IC Controllers-Alternate site for the assembly and test

Products listed in the next page will be assembled in ASE Malaysia with Cu wire

Material	UTAC Thailand	Carsem China	ASE Malaysia (Proposed site)	Impact on Form, Fit or Function
Epoxy	8600	QMI519	QMI519	None
Wire	Au	Cu	Cu	None
Mold compound	G770HCD	G770HCD	G770HCD	None
Terminal Finish	NiPdAu	Ni/Pd/Au	Ni/Pd/Au	None

Reason for the Change:

Additional assembly and test capacity

Effect Date:

Sunday, October 18, 2015

International Rectifier will consider this change approved and will implement it by the effective date unless specific conditions of acceptance or data requests are provided in writing within 30 days of receipt of this notice. Please submit conditions of acceptance and data requests to the PCN coordinator listed at the end of this notice.

Impact of Change:

No impact is expected. The new Bill of Materials and Assembly site will meet the same parametric, MSL and Qualification level as the existing products. Product Datasheets will remain unchanged.

Method of Identifying Changed Product:

The part marking will be updated to include an “underscore” after the last digit of the Lot Code to identify the part as a Copper wire based device.

Products Affected:

IR Part	Description
ASP1257-I16T	
ASP1257-S08T	
IR3580MGB01TRP	
IR3580MTRPBF	
IR3581MDN01TRP	
IR3581MTRPBF	
IR3584MDN01TRP	
IR3588MLN01TRP	
IR3590AMIB01TRP	
IR3590AMTRPBF	
IR3590MIB01TRP	
IR3590MTRPBF	
IR3591MES01TRP	
IR3595AMTRPBF	
IR3595MTRPBF	
IR3596MHA05TRP	
IR3596MTRPBF	
IRMCK099M	
IRMCK099MTR	

Qualification:

Parts passed all the reliability testing requirements. Reliability qualification report is available upon request. Qualification standards can be found on International Rectifier’s web site at www.irf.com/product-info/reliability

Supporting Data Availability:

Contact IR for supporting data on this change.

Contact Information:

CONTACT TYPE	NAME	PHONE	EMAIL
PCN Coordinator	Mark Ogden	+001-951-375-2334	mogden1@irf.com
Technical	Mario Dolores	+6635350803 ext 556	Mario-Antonio.Dolores@infineon.com