PDN Nu	nber:	201	6020500)2			PDN Dat	e:	2/11/2016
Title:	Discon	ntinuance of Select TUSB2046Bxxx devices							
Customer Contact:			PCN Manager				Dept:	Quality Services	
Last date to order:			2/11/2017 Last date			te to	e to ship:		08/11/2017
Change Type:			Product Discontinuance - End Of Life						
Product Discontinuance Notification Details									
Description of Discontinuance: Texas Instruments, Incorporated (TI) is announcing the discontinuance of select									
date shown above. Recommended replacements are being offered as shown in the Product Affected Section. NOTE: There are no samples offered for withdrawn/obsolete products. For assistance on selection of any replacement products or samples, please contact your local sales representative. Reason for Discontinuance: Manufacturing support at ANAM-1 is being discontinued. Shipment history indicates customer programs utilizing TUSB2046B devices are no longer in production therefore, life time buy is offered for service inventory of existing programs.									
Product Affected:									
DISCO	S BEIN	D	PRODU	MMENDED REPLACI CT (REPLACEMENT 41IPAPRQ1 (P)					EPLACEMENT CEMENT CODE)
100BE010BII(IIBI(Q1		TUSB4041IPAPR (P)			Commercial TUSB2046		SB2046	BVFR (Q)	
TUSB2046		4	TUSB40	41IPAPR (P)					BVFRG4 (Q)
P = Sar Q = Sar	nilar fund ne funct me funct	ctiona ionali tionali	lity but r ty but no ty and P	not equivalent. ot pin-for-pin equiva VIN-OUT as the com tionality and param	pared dev	vice b	out is NOT a	an exac	t equivalent.
				notice, e-mails can esentative.	be sent	to th	e regional	contac	ts shown below

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com