

#### 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Туре				
01	002	020	0000000517	0031.5001	Circuit protection	UH	n/a
				0031.5001.G		UH	n/a
				0031.5010		UH tenfold	n/a
				0031.5020		UH	n/a

<sup>\*</sup>SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

#### 2 Type of change

- Change of contact spring material
- Improved electrical contact
- Change of label

## 3 Detailed description of change



## 4 Reason of change

- Improved electrical conductivity and contact resistance
- Configuration code and approval mark added on the label

#### 5 Release date

The change takes effect in ww 05/2021 (Date code 2105 or higher on label).

# 6 Impact of change

Form No No change in form

Fit No No change for dimension

Function Yes Contact resistance reduced

Manufacturing No No change for manufacturing site

Label Yes Configuration code and approval mark on the label

Packaging No No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	UH

Product Change Notification						Product improvement UH		
owner	creation date	release date	released by	change order no	rev	page	D40 044 725	
dislercy	28.04.2020	25.11.2020	bucherfa	2019857	Α	1 of 1	D10-044-735	