



E. Mounting Footprint:




F. Schematic Diagram:

## PRIMARY INPUT CONNECTIONS



## SECONDARY OUTPUT CONNECTIONS



Note:

PREPARED BY:

Required Secondary Fusing. Winding (7-9): T2.50A Winding (10-12): T0.40A

Fuse accordance with IEC60127-2

C. POPPE	Fuse accordance with IEC60127-2			
ENGINEER:	DRAWING CONTROL NO.	REV	MODEL DESCRIPTION	MODEL SPECIFICATION
M. PITCHAI	P-A1-13112	F	POWER TRANSFORMER	PLT30-32-130B
SAFETY ENGINEER	CONTENTS OF THIS DRAWING ARE LAMUKA COKPORATION OF AMERICA			
	SUBJECT TO CHANGE WIT PRIOR NOTICE	THOUT	1040 SOUTH ANDREASEN DRIVE, #100 ESCONDIDO, CA. 92029 (760) 871-2009	DIM: mm[In] SCL: 1/1 SH: 2 0F 2
APPROVED:	PROPRIETARY NOTICE: THIS DRAWING PRINT OR DOCUMENT AND SUBJECT MATTER DISCLOSED HEREIN ARE PROPRIETARY ITEMS TO WHICH TAMURA			
M. PITCHAI			SEMINATION, REPRODUCTION, MANUFACTURE AND SALE. THIS HE RECIPIENT ALONE UNLESS PERMISSION FOR FURTHER	